

CLASSIFIED MESSAGE

~~TOP SECRET~~

DATE 0449Z 21 DEC 62

ROUTING

1	2	3
4	5	6

TO : DIRECTOR

FROM []

~~OPERATIONAL IMMEDIATE~~

OPERATIONAL IMMEDIATE

IN 60054

25X1A ACTION: OPS (1-2-3-4-5)

INFO : S/C (6)

TOR 0456Z 21 DEC 62

EDD 90

WER

KB

RLP

RDO

PAG

SAH

25X1A

TO []

INFO

CITE []

25X1A

A. GRC-133

25X1A

25X1A

B. [] 21/0405Z

25X1A

C. AT D85 THE [] MALFUNCTIONED. UP TO THIS POINT THE

25X1A

FLIGHT LINE WAS UNDERCAST. DRIVER ATTEMPTED TO RECYCLE [] AND SELECTED ALTERNATE MODES SEVERAL TIMES BUT COULD NOT CORRECT THE MALFUNCTION. DRIVER ABORTED AND RETURNED TO HOME AT POINT E50. A.C. GEN FAILED 40 MIN PRIOR TO LANDING. 600 FEET OF FILM WAS EXPOSED. RECOMMENDATION HERE IS THAT WE PROCESS LOCALLY. ADVISE ASAP ON YOUR DECISION. IF YOU AGREE, REQUEST YOU INITIATE ACTION TO CANCEL AIRLIFT.

D. NONE

-END OF MSG-

DOCUMENT NO. _____
 TO CHANGE IN CLASS. ☐
☐ DECLASSIFIED
 CLASS. CHANGE TO: TS (S) C
 NEXT REVIEW DATE: _____
 AUTH: HR 10-2
 DATE: 30 Sept 86 REVIEWER: []

25X1A

~~TOP SECRET~~

GROUP 1
 Excluded from automatic
 downgrading and
 declassification